



# Technical Bulletin

## *Ball float update 2023*

### **FDHF UPDATE**

2023 Updated FOB design to have larger tie rods which required ball floats to be redesigned slightly smaller. At this time we changed suppliers of the ball float to further improve buoyancy.

### **CFD1020/OLD**

Component / FOB / Ball Float ( PRE 2023 MODEL) Left image

### **CFD1020**

Component / FOB / Ball Float ( POST 2023 MODEL) Right image

For more information and product support, contact [equipment@bracton.com](mailto:equipment@bracton.com) or your local Bracton Equipment representative.

